


WIRE CONNECTION DIAGRAM


Wires met safety standards are recommended to connect the supply circuit.

CAUTION: Risk of fire





CANOPY INSTALLATION INSTRUCTIONS

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is turned off and remains off until installation is complete.




Light Bulb (Not included)




(Rated 110-130V/60Hz, bulb 40W-60W maximum.)

Assembly and Installation Steps



Step 6 Group connection wire



- A.8 lines marked with L and the lead marked with I shall be screwed together, screwed with the terminal cap and wound with the electrical tape.
- B.8 wires without mark L and leads without mark I shall be screwed together, tightened with terminal cap, and wrapped with electrical tape.
- C.The wire marked L and the wire marked I of the main wire shall be screwed together, tightened with the terminal cap, and wrapped with electrical tape.
- D.Screw the wire without L mark and the wire without L mark on the main wire together, tighten it with the terminal cap, and wrap it with electrical tape.

Assembly and Installation Steps


Step 7

1. Lock the crossbar to the junction box of the ceiling by using 2 pcs of 5/32 screws in the accessories bag.
2. Connect the wires. The hot/positive (+) wire is the one which has writing on it. The negative (-) wire is the one which has no writing.

Step 8

Hang the lamp to the ceiling by attaching the screws to the nuts.

Adjustable iron position



Please note: The parts in this table are completely unassembled, for illustrative purpose. In the actual product that you receive, some parts are assembled and attached together.

