







ASSEMBLY INSTRUCTIONS

	<p>1</p> <table border="1"> <tr> <td>D x 4 M6x40 mm</td> <td>B x 4 M6/Ø16 mm</td> <td>C x 4 M6</td> <td>E x 1 5 mm</td> </tr> </table> 	D x 4 M6x40 mm	B x 4 M6/Ø16 mm	C x 4 M6	E x 1 5 mm	<p>2</p> <table border="1"> <tr> <td>D x 4 M6x40 mm</td> <td>B x 4 M6/Ø16 mm</td> <td>C x 4 M6</td> <td>E x 1 5 mm</td> </tr> </table> 	D x 4 M6x40 mm	B x 4 M6/Ø16 mm	C x 4 M6	E x 1 5 mm
D x 4 M6x40 mm	B x 4 M6/Ø16 mm	C x 4 M6	E x 1 5 mm							
D x 4 M6x40 mm	B x 4 M6/Ø16 mm	C x 4 M6	E x 1 5 mm							
<p>3</p> 	<p>4</p> <table border="1"> <tr> <td>E x 1 5 mm</td> </tr> </table> 	E x 1 5 mm	<p>5</p> <table border="1"> <tr> <td>A x 4 M6x25 mm</td> <td>B x 4 M6/Ø16 mm</td> <td>C x 4 M6</td> <td>E x 1 5 mm</td> </tr> </table> 	A x 4 M6x25 mm	B x 4 M6/Ø16 mm	C x 4 M6	E x 1 5 mm			
E x 1 5 mm										
A x 4 M6x25 mm	B x 4 M6/Ø16 mm	C x 4 M6	E x 1 5 mm							

Notice: Please tighten screws up initially using fingers only to avoid cross threading the screws