
Assembly Instruction



Attention: Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.




Hardware arts


Α	ॐ	ST4X12	7	
В		M5x40	12	
С	S	M6x34mm	4	
D	9	M6x45mm	6	


	E		M8x55mm	3
	F	2	Ø5x17	4
	G		M8x35mm	14
	Н		4#	1
_			-	


I		5#	1
J	6 9 0	M6x32	12
K		Ø14.8x9.5	12
L	0	Ø6x40	4


Part list

























































Step:7

D	M6x45mm	6
Н	4#	1




*NOTE:Do not tighten all the screws in this step just tighten 75%.


С	M6x34mm	4
Н	4#	1

Step:9

G	M8x35mm	6
E	M8x55	3
I	5 #	1



*NOTE: Tighten the screws that were not tightened before.



*NOTE:Do not tighten all the screws in this step just tighten 75%.

