











ASSEMBLING INSTRUCTION

A X1PC 	B X4PC 	C X1PC 	D X4PC M8X8 	E X8PC M6X16 
F X12PC M8X16 	G X1PC 5# 	H X4PC 	I X12PC 	

STEP 1



Labels: B, G, F//I/E, C


STEP 2

70%



STEP 3


70%



Label: A

STEP 4

100%



Label: H