


































ASSEMBLING INSTRUCTION

SKU NO: EEI-1173

<p>(1)Caster & Base</p> 	<p>(2)Gas Column</p> 	<p>(3)Seat</p> 	<p>A</p>  <p>Diagram A shows the gas column (2) being inserted into the central hole of the base (1). An inset shows two gas columns, labeled 1 and 2, with arrows indicating the correct orientation.</p>																														
<p>(4)Arm</p> 	<p>(5)Mechanism</p> 	<p>(6)Back</p> 	<p>B</p>  <p>Diagram B shows the arms (4) being attached to the base (3) using screws (7-1) and washers (7-2). Screws (7-3) are used to secure the mechanism (5) to the base.</p>																														
<p>(7)</p> <table border="0"> <tr> <td>1.</td> <td></td> <td>x4</td> <td>1/4"x1-3/4"</td> </tr> <tr> <td>2.</td> <td></td> <td>x2</td> <td>1/4"x1-3/8"</td> </tr> <tr> <td>3.</td> <td></td> <td>x10</td> <td>Φ16x6xT1mm</td> </tr> <tr> <td>4.</td> <td></td> <td>x4</td> <td>1/4"x1"</td> </tr> <tr> <td>5.</td> <td></td> <td>x3</td> <td>5/16"x3/4"</td> </tr> <tr> <td>6.</td> <td></td> <td>x3</td> <td>Φ21xΦ10xT2mm</td> </tr> <tr> <td>7.</td> <td></td> <td>x1</td> <td>5mm</td> </tr> </table>			1.		x4	1/4"x1-3/4"	2.		x2	1/4"x1-3/8"	3.		x10	Φ16x6xT1mm	4.		x4	1/4"x1"	5.		x3	5/16"x3/4"	6.		x3	Φ21xΦ10xT2mm	7.		x1	5mm	<p>D</p>  <p>Diagram D shows the backrest (6) being attached to the mechanism (5) using screws (7-5) and washers (7-6).</p>		
1.		x4	1/4"x1-3/4"																														
2.		x2	1/4"x1-3/8"																														
3.		x10	Φ16x6xT1mm																														
4.		x4	1/4"x1"																														
5.		x3	5/16"x3/4"																														
6.		x3	Φ21xΦ10xT2mm																														
7.		x1	5mm																														
			<p>E</p>  <p>Diagram E shows the backrest (6) being attached to the base (3) using screws (7-5) and washers (7-6).</p>																														
			<p>F</p>  <p>Diagram F shows the seat (3) being inserted into the gas column (2) and pushed down to lock it in place.</p>																														