


# 10x14FT WALL GAZEBO

---

---























## **TIPS:**





















You will receive two separate boxes to fully assemble this product, the boxes may arrive at different times. Please make sure all boxes arrive in good condition before assembling.

Thank you very much for your patience!









## **ATTENTION:**


1. Please check the manual carefully and make sure you have received all the parts.
2. If there is any missing, please let us know the letter of the parts you need.
3. If there is any damage, please send clear photos to us, we will check and offer you best solution soon.

PART	NO.	QTY.
	A1	1
	A3	1
	B1	1
	B2	1
	B3	1
	C	5
	L	5
 (M6X15)	W	179
	M	12
 (M6X70)	Z2	10
	Z3	5
	D1	2
	D2	2
	D3	2
	N	4
 (M8X35)	Y	20
	Z4	1
	Z6	20
	O	3
	P	3





PART	NO.	QTY.
	S	8
	T	8
	E1	8
	E2	8
 (M6X50)	Z1	32
	Q	16
 (M6X30)	X	27
	H	8
	I1	1
	I2	1
	I3	1
	I4	1
	J	3
	K1	14
	G	7
	R	16
	F	14
	U	4
	V	18
 (M6X60) Expansion screws	Z5	6


1

PART	NO.	QTY.
	<b>A1</b>	1
	<b>A3</b>	1
	<b>B1</b>	1
	<b>B2</b>	1
	<b>B3</b>	1
	<b>C</b>	5
	<b>L</b>	5
	<b>W</b>	40



2






PART	NO.	QTY.
	<b>M</b>	12
	<b>Z2</b>	10
	<b>W</b>	2
	<b>Z3</b>	5




1








3

PART	NO.	QTY.
	<b>D1</b>	2
	<b>D2</b>	2
	<b>D3</b>	2
	<b>N</b>	4
	<b>W</b>	32



4




PART	NO.	QTY.
	<b>Y</b>	20
	<b>Z4</b>	1
	<b>W</b>	1
	<b>Z6</b>	20




2









5

PART	NO.	QTY.
	O	3
	P	3
	W	24








6

PART	NO.	QTY.
	S	8
	T	8
	E1	8
	E2	8
	Z1	32



7


PART	NO.	QTY.
	<b>Q</b>	16
	<b>X</b>	16
	<b>W</b>	32
	<b>H</b>	8









The direction of the Q components at both ends must be in the same direction


8

PART	NO.	QTY.
	<b>W</b>	32





9

PART	NO.	QTY.
	<b>I1</b>	1
	<b>I2</b>	1
	<b>I3</b>	1
	<b>I4</b>	1
	<b>X</b>	3
	<b>J</b>	3






10

PART	NO.	QTY.
	<b>X</b>	8




11




PART	NO.	QTY.
	<b>K1</b>	14
	<b>G</b>	7





NOTE: There is a leakage hole with one side facing upwards






12

PART	NO.	QTY.
	<b>R</b>	16
	<b>F</b>	14
	<b>W</b>	16





13


PART	NO.	QTY.
	<b>U</b>	4
	<b>V</b>	18



14

PART	NO.	QTY.
	<b>Z5</b>	6





Carton-1/2			
PART	QTY.	PART	QTY.
A1	1	S	8
A3	1	T	8
B1	1	Z1	32
B2	1	Q	16
B3	1	X	27
C	5	H	8
L	5	I1	1
W	179	I2	1
M	12	I3	1
Z2	10	I4	1
Z3	5	J	3
D1	2	G	7
D2	2	R	16
D3	2	F	14
N	4	U	4
Y	20	V	18
Z4	1	Z5	6
Z6	20		
O	3		
P	3		

Carton-2/2	
PART	QTY.
K1	14
E1	8
E2	8