











| | | |
|--|--|---|
| An icon showing an L-shaped metal bracket inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used. | A warning triangle containing an exclamation mark. | A clock face showing approximately 12:30. |
| An icon showing a rectangular block on a surface with a hatched pattern. To its right is the same block with a screw being inserted into it, crossed out with a diagonal line. | A warning triangle containing an exclamation mark. | A simple line drawing of a person. |
| | | 30' |
| | | 1 |



1



2





3

E
M6
x
15
x 2



G
x 2

I
x 1



4

H
x 4





5

E
M6
x
15
x2






G
x2

I
x1



6

I
x1



7

