


WIRE CONNECTION DIAGRAM


Wires met safety standards are recommended to connect the supply circuit.

CAUTION: Risk of fire




CANOPY INSTALLATION INSTRUCTIONS

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is turned off and remains off until installation is complete.



Light Bulb (Not included)



GU10

USER MANUAL FOR MODEL# 16003

Dear Customer


Thank you for yor business!

If you have any question or problem, please text or call us at 870-9498466. We want you to be completely satisfied with your purchase.

Product review means the world to us, if you want to share your experience you can leave a short product review.

Thank you

Zgear Team



(Rated 110-130V/60Hz, bulb 35W-60W maximum.)

Assembly and Installation Steps

Step 1

- 1A. Lock the crossbar to the junction box of the ceiling by using 2 pcs of 5/32 screws in the accessories bag.
- 1B. Connect the wires. The hot/positive (+) wire is the one which has writing on it. The negative (-) wire is the one which has no writing.

Step 2

There are 4 screws and 4 nuts in the plastic bag. Hang the lamp to the ceiling by attaching the screws to the nuts.

Step 3

Install 5 GU10 bulbs (Not included).

Step 4

Buckle the crystal ball and hang the crystal string on the metal ring.

Suggested installation sequence from 6 to 1

Please note: The parts in this table are completely unassembled,for illustrative purpose. In the actual product that you receive, some parts are assembled and attached together.

