



NOTE: The hardware packaging is in a red plastic bag and hung at both ends of the box. If you cannot find it, please try searching on the inside of both ends of the box. Please check whether the screws are loose every 3-6 months and tighten the screws.

PDXJ531

ASSEMBLY INSTRUCTION

Attention: Do not tighten the screws until all of them are in right positions. Please contact us if you are missing any of the parts, or if you have a damaged part. Please let us know the part number. We will offer good solution asap.
Customer service E-mail: cservice7@yeah.net
Please attach your Order ID so that we can assist you better.

① X1



② X2



③ X1



A X12+2



M8X40mm

B X1



C X12+2



φ16X8X0.5mm

D X8+2




φ25X4mm

STEP 1

AX8 C X8




Please tighten the screws to 70% first, and tighten all screws 100% after all parts are assembled.



STEP 2

AX4 C X4



STEP 3

D X8

