




Assembly instruction box 1:








- Icon: An L-shaped metal bracket inside a circle.
- Icon: A power drill with a slash through it, indicating it should not be used.
- Warning icon: A triangle with an exclamation mark.
- Time icon: A clock face.
- Time text: **20'**

Assembly instruction box 2:

- Icon: A rectangular block being placed on a textured surface inside a circle.
- Icon: A rectangular block with a slash through it, indicating it should not be used.
- Warning icon: A triangle with an exclamation mark.
- Person icon: A simple human figure.
- Person text: **1**



1



2

