















Assembly Manual







T 25




K14




2




**DO NOT USE A HAMMER ,
YOU CAN INSERT IT WITH
A SOFT TOOL**




3



4



5



6