









Diagram illustrating the tools and safety requirements for a task:


- Tools:** A pencil, a marker, a tape measure, and a power drill.
- Warning:** A warning triangle with an exclamation mark.
- Time:** A clock icon indicating a duration of 20 minutes.
- Personnel:** A person icon indicating that 1 person is required.
- Material:** A diagram showing a rectangular block being placed on a surface, with a second diagram showing the block being secured with a screw.
- Warning:** A second warning triangle with an exclamation mark.




1





!



!



2



3

