



































Assembly Instructions









<p>Ⓐ X 2</p> 	<p>Ⓑ X 2</p> 	<p>Ⓒ X 1</p> 	<p>Ⓓ X 2</p> 
<p>Ⓔ X 1</p> 	<p>Ⓕ X 1</p> 	<p>Ⓖ X 1</p> 	<p>Ⓗ X 2</p> 
<p>Ⓘ X 2</p> 	<p>Ⓙ X 2</p> 	<p>Ⓚ X 2</p> 	<p>Ⓛ X 1</p> 
<p>Ⓜ X 1</p> 	<p>Ⓝ X 1</p> 	<p>Ⓞ X 1</p> 	<p>Ⓟ X 3</p> 
<p>X 47</p> 	<p>X 2</p> 		
<p>① X 11</p>  <p>M6*100mm</p>	<p>② X 23</p> 	<p>③ X 17</p>  <p>10*50mm</p>	<p>④ X 12</p>  <p>M6*60mm</p>
<p>⑤ X 8</p> 	<p>⑥ X 8</p> 	<p>⑦ X 35</p>  <p>15mm</p>	<p>⑧ X 8</p> 
<p>⑨ X 30</p>  <p>25mm</p>	<p>⑩ X 1</p> 	<p>⑪ X 8</p> 	<p>⑫ X 1</p> 
<p>⑬ X 1</p> 			

1






2





M6*100MM
① X 8 PCS

② X 8 PCS

10*50MM
③ X 8 PCS



3





M6*60MM
④ X 6 PCS

② X 6 PCS



4





⑤ X 8 PCS

⑥ X 8 PCS


7





M6*60MM
④ X 3 PCS

② X 3 PCS

8







25MM
⑨ X 29 PCS

9




10









M6*60MM
④ X 2 PCS

② X 2 PCS

11





12






M6*100MM
① X 1 PCS

M6*60MM
④ X 1 PCS

② X 2 PCS

10*50MM
③ X 1 PCS

13



14



15

