Assembly Instructions			
Please install the products on carpet or soft place			
Parts List			
No.	Sketch	Description	Qty
А		Glass Top	1
В	Ú.	Leg	4
С	005	Iron Box	1
D		Adjustable Feet	4
Hardware List			
No.	Sketch	Description	Qty
1		Bolts M8x16	8
2		Bolts M8x8	4
3		Offset Ring Spanner	1
4		Allen Key	1
5	ß	Plastic Protection Corner	4









