



Connect the table leg frames as shown in the picture




Ir on fr ame scr ew

36 PCS


Fix and lock the ir on fr ame cr ossbeam and the table legs with flat-head scr ews



Self-tapping screw



28 PCS



Cover the tabletop,
then insert self-
tapping screws
through the holes at
the bottom of the
frame and secure the
tabletop.