


Assembly Instructions

Lamp Table



Keep these instructions for future reference

WARNING

Read instructions carefully. Check no parts are missing.

Assemble the furniture on a soft level surface to avoid damaging the furniture or your floor.

Carefully identify each component, especially those that are similar.


The most common mistake is getting things back to front.

Separate and identify each component from the hardware pack and rest each one in it's proper location before fastening.

We recommend furniture be assembled near where they will be placed, to avoid moving the product unnecessarily once assembled.



If there is a need to move the furniture, please remove all loose items and have extra hands to help lift the furniture to the desired location. Dragging the furniture will damage both the furniture and the floor.

Regularly check and re-tighten (if necessary) all bolts on furniture that you have assembled yourself.




ALLOW 30 MIN


1 Person Required



DO NOT USE ON PRODUCT















Tools Required






CHECKLIST



A <input type="checkbox"/>  $\varnothing 6 \times 35$ mm Ax26	B <input type="checkbox"/>  $\varnothing 15$ mm Bx22	C <input type="checkbox"/>  $\varnothing 12$ mm Cx4	D <input type="checkbox"/>  $\varnothing 8 \times 32$ mm Dx26	E <input type="checkbox"/>  $M7 \times 50$ mm Ex4
F <input type="checkbox"/>  350 mm Fx1	G <input type="checkbox"/>  $M6.5 \times 10.5$ mm Gx4	H <input type="checkbox"/>  $M3.5 \times 13$ mm Hx6	I <input type="checkbox"/>  $M8 \times 39$ mm Ix4	J <input type="checkbox"/>  $9 \times 10 \times 14$ mm Jx4
K <input type="checkbox"/>  $M3.5 \times 15.5$ mm Kx4	L <input type="checkbox"/>  L4 Lx1	M <input type="checkbox"/>  $M6 \times 25$ mm Mx2	N <input type="checkbox"/>  $25 \times 25 \times 2$ mm Nx4	


1



Ax8











Dx12



Fx1




Gx4



2




Bx2




3




Bx2




4



Ax4





5



Ax4




Dx12



6




Bx4



7




Ax6



8



Bx3




9




Bx3




Nx4



10




11



12



Bx4





13



Jx4



Kx4



11-13


14




Ax4



Cx4



15




Fx1




Ix4



Hx6



16



17

