







# Assembly Instruction






# PLATE NUMBER




# ACCESSORIES LIST

A ×138



M6×35

B ×138




12×10

C ×47




M5×40

D ×128



M3×12

E ×8




M300

F ×18




M3.5×12

G ×1




H ×26




M4x12

J ×16



M4x14


K ×1




L ×12




M ×2




N ×2



P ×14




Q ×14




M3.5×14


R ×1



S ×2




T ×8






M96

×1







# STEP1






Dx12

# STEP2









Iron Rod A is prohibited from using an electric drill.









Ax5

# STEP3





Bx3

# STEP4



Bx2

# STEP5









E-CLx3





Dx12

# STEP6

Iron Rod A is prohibited from using an electric drill.









180°






Ax7

# STEP 7



# STEP8







E-CLx4






Dx16

# STEP9









Iron Rod A is prohibited from using an electric drill.









Ax7

# STEP10









Bx3

# STEP11







Bx4





# STEP 12



# STEP 13









Iron Rod A is prohibited from using an electric drill.





Ax13

# STEP14










Bx7

# STEP15






STEP 16



Ax8

# STEP17









E-CRx1









Dx2

# STEP18









Ax4







# STEP19



# STEP20









# STEP21



**Bx4**

# STEP22




**Bx4**









**Cx2**

# STEP23










# STEP24




Ax17

# STEP25









Ax32









K-1x1

# STEP26




Bx9

# STEP27









Bx10

# STEP28









Lx5

# STEP29









Bx7







# STEP30



# STEP31





# STEP32









Bx2

# STEP33




Lx7

# STEP34







Bx15





# STEP35



# STEP36









Iron Rod A is prohibited from using an electric drill.









Ax10

# STEP37





Bx6

# STEP38



Bx8

# STEP39






Fx2





Gx1




# STEP40




Hx26



# STEP41




		
Fx4	K-2x1	Mx2

# STEP42









	
Dx1	Nx1

# STEP43






Adjusting the hole indicated on this hinge can move the mirror panel forward or backward.







			
<b>Dx1</b>	<b>Fx4</b>	<b>Nx1</b>	<b>x1</b>


# STEP44



# STEP45x4




Iron Rod A is prohibited from using an electric drill.









Ax16	Jx8	Tx4

# STEP46x4






Cx16

# STEP47x4




**Bx16**


# STEP48x4



**E-DLx4**







**E-DRx4**







**Dx32**

# STEP49x3





Iron Rod A is prohibited from using an electric drill.








		
Ax12	Jx6	Tx3

# STEP50x3






Cx12

# STEP51x3




# STEP52x3







E-DLx3




E-DRx3






# STEP53





Iron Rod A is prohibited from using an electric drill.









		
Ax5	Jx2	Tx1

# STEP54










Cx5


# STEP55




# STEP56





E-DLx1









E-DRx1



# STEP 57





# STEP58





Rx1

# STEP59



<b>Cx12</b>	<b>Fx4</b>	<b>Sx2</b>

# STEP60



<b>Fx4</b>