
Assembly Instructions







Please contact us by scanning the QR code to get more services if there is any problem with the item rather than returning the parcel directly.


HARDWARE LIST





	X				or and o
A = 38	B = 38	C = 4	D = 48	E = 2	F = 2
	0	\bigcirc			
G = 2	H = 2	I = 2	J = 2	K = 5	







Please note that the holes on panels (1), (2), and (3) are facing down. Please ensure the correct orientation to avoid installation errors!









()







Finish!