

# Annual Maintenance for Outdoor Tables

## Materials Needed:

- Varathane Clear Satin Spar Urethane Spray # 250281
- Clean, lint-free cloths
- Mild soap and water
- Protective gloves
- Drop cloth or newspapers

## Steps:

### 1. Preparation:

- Clean the Table: Wipe down the table with a mixture of mild soap and water to remove any dirt, dust, or debris. Rinse with clean water and let it dry completely.

### 2. Application of Varathane Clear Satin Spar Urethane Spray:

- **Set Up:** Place the table on a drop cloth or newspapers in a well-ventilated area. Wear protective gloves to avoid contact with the spray.
- **Shake the Can:** Shake the Varathane Clear Satin Spar Urethane Spray can vigorously for about one minute to ensure it is well-mixed.
- **Test Spray:** Test the spray on a small, inconspicuous area to ensure compatibility and desired finish.
- **Apply the First Coat:** Hold the can 10-12 inches away from the surface and spray in a steady, back-and-forth motion, slightly overlapping each stroke. Apply a light, even coat.
- **Drying Time:** Allow the first coat to dry for at least 30 minutes. The finish should be dry to the touch.
- **Apply Additional Coats:** Repeat the spraying process for a total of at least 4 coats, allowing each coat to dry and sanding lightly between coats. This will provide maximum durability and UV protection.

### 3. Final Steps:

**Cure Time:** Allow the final coat to cure for at least 24 hours before using the table.

**Regular Maintenance:** Clean the table regularly with mild soap and water.