


Assembly Instruction Sheet

Corner Bookcase



List of Parts


NO.	Description	Q'ty
A	SHELF A	1
B	SHELF B	1
C	SHELF C	1
D	SHELF D	1
E	SHELF E	1
F1	TOP FRAME LEFT	1
F2	TOP FRAME RIGHT	1
G1	BOTTOM FRAME LEFT	1
G2	BOTTOM FRAME RIGHT	1

List of Hardware

Screw JCA 1/4" x 32 RF10003 21 pcs.	Screw P6 x 5/8" RF10080 2 pcs.	Metal Plate RF40214 1 pc.	Allen Wrench RF40015 1 pc.


Anti-Tipping

Screw P6 x 5/8" RF10080 2 pcs.	Screw P6 x 1 1/4" RF10103 2 pcs.	Metal Plate RF40214 2 pcs.




Step 1.

Attach shelf (A) and shelf (B) into the top frame left (F1) using screws (RF10003). Then attach the top frame right (F2) into them using screws (RF10003) as per Diag.1.



Step 2.

Attach shelf (C), (D) and (E) into the bottom frame left (G1) using screws (RF10003). Then attach the bottom frame right (G2) into them using screws (RF10003) as per Diag.2.



Step 3.

Stacking the top unit onto the bottom unit. Then attaching the metal plate (RF40214) to the predrilled holes at the back of the bookcase using screws (RF10080) as per Diag.3.

Anti-Tipping

Use metal plate (RF40214) and screws P6 x 5/8" (RF10080) to attach two side panels thru the studs into the wall, using screws P6 x 1 1/4" (RF10103) as per Diag. 5.

