







Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing an L-shaped metal bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this step.
- Warning 2:** A triangle with an exclamation mark points to a box containing a rectangular block on a textured surface and a crossed-out icon of the block being lifted, indicating that the block should not be lifted or moved in a certain way.
- Time:** A clock icon is positioned to the right of the first warning, with the text "15'" below it, indicating a 15-minute time limit for this step.
- Person:** A stick figure icon is positioned to the right of the second warning, with the text "1" below it, indicating that one person is required for this step.



1



2

