



Assembly Instruction

φ400*H500 L6



- 1.Pass pin through the hole of crystal
- 2.Bent the pin into the shape as picture.
- 3.Hang crystal to the hole of frame.




(Fig 2-1)

NO.	Parts name and specification	qty
A	14# beads*11	12PCS
B	22*76 glass rod	73PCS
C	40# crystal ball	37PCS

Assembly step:

- 1.Attached mounting strap to the ceiling and secure with expansion screws (Note ceiling enough to load capacity.)
2. Attached lamp arms to the holes of middle box and secure with nut and connect fixture as Fig.2-2.
3. Connection wires from lamp arm to the wires from middle of rod as Fig.2-2.
- 4.Connection first layer frame with bottom of frame with 6*55 rod as Fig.2-1.
- 5.Cut off the power. hook lamp body to the hook of ceiling. connection the wire from lamp with power from ceiling.
- 6.Assembly all lamp bulbs to the lampholder and test lamps.
7. Hang crystal to the hole of frame according to Fig 2-1 (From top to bottom, from inside to outside.)



(Fig 2-2)

Safety Instruction

1. The lamp is suitable for 85-265V power supply
2. When installing, please wear gloves.
- 3.Please do not install on damp ceiling.
4. When cleaning, please cut off the power supply
5. Be sure to ask professional electrician to install
6. Pls refer to max wattage and type of bulb on lamphodler label.