


# INSTRUCTION MANUAL

## INSTALLATION:

1. SHOT DOWN THE POWER.
2. THREAD THE 2 LONG SCREWS INTO THE CROSSBAR , AND ATTACH THE CROSSBAR TO THE OUTLET BOX WITH THE SHORTER SCREWS.
- 3.MAKE THE WIRE CONNECTIONS.CONNECTBLACK TO BLACK WIRE AND WHITE TO WHITE WIRE. IF THE WIRES ARE NOT BLACK ANDWHITE, CONNECT THE BLACK WIRE IN THE OUTLET BOX TO THE PLAIN OR ROUNDED SIDE OF THE FIXTURE WIRE.CONNECT THE WHITE WIRE IN OUTLET BOX TO THE RIBBED WIRE OF THE FIXTURE WIRE.ATTACH GROUNDING WIRE TO CROSSBAR GROUNDING SCREW.
4. ALIGN THE HOLES IN THE FIXTURE WITH THE 2 LONG SCREWS IN THE CROSSBA, ANDPLACE THE FIXTURE ONTO THE SCREWS.SECURE THE FIXTURE IN PLACE WITH THE NUTS.
5. SECURE SHADE TO LAMPHOULDER WITH THE RETAINING RING.
- 6.INSTALL A LED BULB INTO THE SOCKET.



**The above illustration is similar to the actual product.**

## WARNING:

1. If the cable is damaged, do not use the lamp. For repair, take the lamp to a certified electrical workshop.
2. If your lamp remains turned on for a prolonged time, the lamp shade (glass, cap, bulb, etc.) will become hot, please do not touch until be cooler ,, and test it carefully before handling it.
3. When installing or replacing bulb, be sure that the Lamp Turn Off first
4. Maximum 60 wattage
5. This lamp is for indoor use only.

**CLEANING & CARE:** To clean the shade, remove dust with either a paper towel or a duster—no household cleaners are needed. Occasionally, a white powder may appear on the soldering, as a result of Oxidation. To restore the soldering to its original condition, apply a small amount of Lemon or Mineral Oil to the affected area. Remove the oil with a paper towel. Do not use chemical cleaner.