



Assembly Instructions

Option 1



Option 2




Special Warnings

- Keep your furniture out of direct sunlight. Please use desk pads and coasters to protect the surface from dents, scratches, and moisture from hot or cold liquids.
- For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth. Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.


Operation Instructions

- Please check that all parts are present before you start the assembly of your furniture. For the protection of your furniture, place all parts on a clean and smooth surface to prevent any damage.
- Please periodically check all fitting and re-tighten as necessary.
- **Please assemble the table by 2 persons or more.**
- Do NOT over tighten hardware.


①




②




③




④




⑤




⑥




⑦



⑧



⑨



⑩




⑪




⑫




⑬



⑭




⑮




⑯




⑰




⑱




⑲




⑳



㉑





22





14"

23




3 Hours




Part.	Item.	QTY.	
A	M5X45	32	
B		32	
C	M3.5X14	22	
D	M5X40	22	
E	M6X40	2	
F	M6	2	
G	M6X45	2	
H	M4X20	4	
I	M4X96	2	
J	M6X25	2	
K	M3X25	4	
L		4	
M		2	
N		1	
			
			

5X45mm bolt installation as below




1



.SCREWS

A M5X45
2 PCS

2




.SCREWS

C M3.5X14
2 PCS

.SCREWS

N 1 PCS


3



.SCREWS

D M5X40
1 PCS

4




.SCREWS

A M5X45
2 PCS

.SCREWS

C M3.5X14
2 PCS


5



.SCREWS

D M5X40
1 PCS

6





.SCREWS

D M5X40
2 PCS

7

.SCREWS




B  M5X45
2 PCS 



8

.SCREWS



B  M5X45
A  6 PCS




9

.SCREWS


B  M5X45
2 PCS 



10




.SCREWS
B M5X45
A 6 PCS



11


.SCREWS
D M5X40
10 PCS



12



.SCREWS
K M3X25
4 PCS

.SCREWS
L 4 PCS



13

.SCREWS
B M5X45
A 10 PCS




14

.SCREWS




B M5X45
A 2 PCS

.SCREWS

M ϕ 6X40
2 PCS






*Hammer isn't inside
Accessory Pack.



15

.SCREWS

B M5X45
A 4 PCS



16

Option 1 ☐

.SCREWS



E M6X40
2 PCS

.SCREWS

F M6
2 PCS


.SCREWS

G M6X45
2 PCS





.SCREWS		.SCREWS		.SCREWS	
E	M6X40	F	M6	G	M6X45
	2 PCS		2 PCS		2 PCS


Option 2 ☐




17



.SCREWS	
H	M4X20
	2 PCS
.SCREWS	
I	1 PCS
	
.SCREWS	
C	M3.5X14
	12 PCS



18




.SCREWS


D M5X40
4 PCS



19



20




.SCREWS

D M5X40
4 PCS



21




.SCREWS

J M6X25
2 PCS



22



.SCREWS

H M4X20
2 PCS




.SCREWS

I 1 PCS



23




.SCREWS

C M3.5X14


4 PCS

24



25

Option 1 ☐



Option 2 ☐

