




EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

**FR_IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION
ULTÉRIEURE.**


ES_IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.

PT_IMPORTANTE, RETER PARA REFERÊNCIA FUTURA: LEIA ATENTAMENTE.


DE_WICHTIG! SORFGFÄLTIG LESEN UND FÜR SPÄTERES NACHSCHLAGEN AUFBEWAHREN.

**IT_IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E
LEGGERLO ATTENTAMENTE.**


PARTS




A




B




C




D



E*2



F




G



H*3

HARDWARE



3.5*30mm 14+1PCS

S1




3.5*20mm 10+1PCS

S2



2.0*3mm 16+1PCS

S3



6PCS

S4



8PCS



S5




6PCS

S6



01


A x01**B** x01**C** x01**S1** x06

3.5*30mm




02


D x01**S4** x06

E x02**S5** x08**S3** x08


2.0*3mm




02



03

**S3** x04

2.0*3mm




05

01



04



S1 x04




3.5*30mm

S3 x04



2.0*3mm




06

05




F x01





S1 x04




3.5*30mm





06

**G** x01**S2** x10

3.5*20mm



07

**H** x03**S6** x06**S6** * 2

x3

Done