























①  x1	②  x1	③  x1	④  x1	⑤  x1
⑥  x1	⑦  x1	⑧  x1	⑨  x1	⑩  x1
⑪  x1	⑫  x2	A  M6x35 x32		B  Ø12 x32
C  M5.2*64 x4	D  Ø15 x8	E  M4x30 x4	F  M4x12 x54	G  M6x30 x8
H  M8x40 x4	J  x4	K  x2	M  x5	P  M5x60  8x60 x4
Z  Ø15 x40				



1





2




3



4




5




	A	x2
	G	x4

6




	A	x2
	G	x4

7





8





	F	x3
---	---	----



9





10




11



12




13




	B	x4
---	---	----

14




	B	x2
---	---	----

15




	E	x4
	B	x4

16




	B	x4
---	---	----

17




	H	x2
	C	x2
	D	x4

18




	B	x8
---	---	----

19




	B	x6
---	---	----

20




	F	x20
	M	x5

21




	F	x6
	J	x2

22



	F	x6
	J	x2

23



	F	x8
---	---	----

