







ASSEMBLY INSTRUCTION


P1		6x50 mm 8PCS+1spare
P2		4.0x45 mm 16PCS+1spare
P3		3.5x35 mm 16PCS+1spare
P4		3.5x25 mm 20PCS+1spare
P5		3.0x16 mm 12PCS+1spare
P6		




(A)x1




(B)x1




(C)x1




(D)x1



(E)x1




(F)x2




(G)x2




(H)x1




(I)x1



(J)x1




(K)x1




(L)x1



(M)x1




(N)x1




(O)x2




(P)x2




(Q)x1



(R)x2



step1



step2