



Assembly Instruction

Note:


- 1. Should be assembled on flat ground to keep balance.**
- 2. Before completing the installation, do not tighten the screws.**







It needs at least two people to install.



Before starting the assembly, you must read the whole manual and follow the instructions.















Hardware arts

 (A) M6x12 4pcs	 (B) M6x20 4pcs	 (C) M6x30 10pcs	 (D) M8x35 12pcs	 (E) M8x55 4pcs	 (F) $\phi 5 \times 35$ 8pcs	 (G) $\phi 4 \times 10$ 2pcs	 (H) 4 # 1pc	 (I) 3 # 1pc	Page 2/8
---	---	--	--	---	--	--	--	--	-----------------


Assembly Instruction

Part list


					
① 2 PCS	② 1 PC	③ 1 PC	④ 2 PCS	⑤ 2 PCS	⑥ 2 PCS
					
⑦ 1 PC	⑧ 2 PCS	⑨ 8 PCS			⑫ 1 PC
					
⑬ 1 PC	⑭ 1 PC	⑮ 1 PC	⑯ 1 PCS		

Assembly Instruction

G	 $\phi 4 \times 10$	2pcs
H		1pc




A	 M6x12	4pcs
H		1pc




Assembly Instruction

C	 M6x30	6pcs
E		1pc




B	 M6x20	4pcs
F	 $\phi 5 \times 35$	8pcs
H		1pc
I		1pc




Assembly Instruction

E	 M8x55	4pcs
H		1pc





D	 M8x35	8pcs
H		1pc



Assembly Instruction

C	 M6x30	4pcs
H		1pc



Assembly Instruction

D	 M8x35	4pcs
H		1pc

