
ASSEMBLY INSTRUCTION **DESCRIPTION** Executive Desk Top/base

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have some loose inside the carton during shipment. Identify and count all parts and compare with the parts List Below:



ASSEMBLY INSTRUCTION

DESCRIPTION

Executive Desk Top/base


Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have some loose inside the carton during shipment. Identify and count all parts and compare with the parts List Below:

PARTS LIST

| AKTO LIOT | | | |
|-----------|--------|---------------|-----|
| NO. | SKETCH | DESCRIPTION | QTY |
| Α | 0 | TOP | 1 |
| В | / | PENCIL HOLDER | 1 |
| С | | LEFT BASE | 1 |
| D | | RIGHT BASE | 1 |
| E | 0 | BACK PANEL | 1 |

PARTS LIST

| NO. | SKETCH | DESCRIPTION | QTY |
|-----|--------|----------------------|-----|
| F | 0 | GROMMET | 1 |
| G | \ | BOLT Ø5/16* | 12 |
| Н | 0 | SPRING WASHER Ø5/16* | 12 |
| ľ | 0 | FLAT WASHER Ø5/16" | 12 |
| J | ~ | ALLEN KEY Ø5/16" | 1 |
| к | 0 | WOOD DOWEL | 8 |



Attention: Please note all bolt locations follow the sequence in asembly.

Step 1.Put wood dowel locators (K) In the right position at base (C) ,Base (D) and back panel(E).Assemble the Base(C) ,Base(D) and back panel (E) by Flat washer(I), Springwasher(H) ,bolt (G)and allen key (J) according to the following picture details.

Step 2:Put the gommet (F) in the hole on top.

Step 3:After setting up , you can level the desk by adjusting leveler at each corner.

Note: Wire access cord is to follow above sketch.

MADE IN CHINA