



Per properly installed bracket



Measure carefully before you purchase



We recommend you consult an expert

Steel Support Bracket

Measuring Guide

How many brackets do you need?

1. Determine the length of the surface you want to support (A)

2. Divide that length by your desired bracket spacing (C). 24"-36" between brackets is typical, but the best spacing will vary depending on your application. Please consult a professional if unsure.

3. Add one bracket. This is your bracket count.

Example: A 72" long countertop divided by 24" bracket spacing = 3, add 1 more bracket to get a final count of 4 brackets.



Pro Tip: Designers recommend 24" + between bar seats for comfort. If your installation requires closer spacing, consider our hidden brackets.