








NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS & SCREWS


COMPONENTS LIST

I



Q'TY 1

II



Q'TY 4

HARDWARE LIST


A



8

Hex. Nut


C



1

Spanner


B




8

Washer


Step 1



Step 2



Step 3



Step 4

