# NOTICE

- \* Please make sure that you have all parts indicated and are in good condition before you begin assembly of this item. Refer to part list and hardware list below for guidance.
- \* This item should be assembled on a soft surface to prevent scratching the finish during assembly.
- \* This item may require periodic tightening.

### **PREPARATION**

- \* Before beginning assembly of product, make sure all parts are present. Compare parts with parts contents list and hardware contents list.
- \* If any part is missing or damaged, do not attempt to assemble the product.
  \* Estimated Assembly time: 10 minutes
  \* Tools Required for Assembly (included): Allen key

## CARE AND MAINTENANCE

- \*Spot clean using a mild water-free solvent. Only a professional cleaner should undertake a complete overall cleaning.
- \*The use of steam or water-based cleaners may cause excessive shrinking or staining.

#### Part List and Hardware List

PIECE	DESCRIPTION	PICTURE	QUANTITY
А	Table Top		1X
В	Leg		2X
Hw1	Allen bolt 6 X 25 mm		16X
Hw2	Flat washer 16 x 8 mm		16X
Hw3	Allen key 4 mm		1X

Product dimensions: 39"W\* 18"D\* 30"H





WARNING




Weight Capacity - 110 LBS


Warning: Do not stand on Table Warning: Do not over torque bolts.

# **PREPARATION**


- \* Before beginning assembly of product, make sure all parts are present. Compare parts with part contents list and hardware contents list.
- \* If any part is missing or damaged, do not attempt to assemble the product.
- \* Estimated Assembly time : 10 minutes
- \* Tools Required for Assembly (included): Allen key




**STEP1** Unwrap the legs(B) and remove them from the packaging. Take out the hardware from the hardware packet.




STEP2 Place the table top (A) upside down on a soft, clean surface. STEP3 Put the Flat washer(HW2) on the Allen Bolt Align the screw holes on the legs (B) with the screw holes on the table top (A).



(Hw1) as shown.



**STEP4** Attach the legs(B) to the table top (A) by using the Allen key (Hw3) to screw in the bolts and washer from step 3. Don't over tighten



**STEP5** Repeat step 4 for the second leg. Turn the table upright. Product is now ready for use.