













				
Ax36	Bx36	Cx4	Dx12	Ex6
				
Fx11	Gx12	Hx2	Ix6	Jx2
				
Kx2	Lx4			

Step 1



	Bx7
	Dx2
	Ex1





Step 2



	Bx7
	Dx2
	Ex1

Step 3





x2



	Dx4
	Ex2


Step 4

x2




	Dx4
	Ex2


Step 5



Step 6




Step 7




Fx3

Step 8




Ax4

Step 9




	Ax3
	Cx2

Step 10




	Ax7
	Cx2


Step 11




Step 12




Step 13



Step 14




Step 15





	I x 6
---	-------

Step 16



	J x 2
	K x 2
	L x 2

Step 17



	Fx2
	Lx2
	Hx2