



ASSEMBLY INSTRUCTIONS




PARTS IDENTIFICATION

A




2pcs

B




1pc

C



1pc

D



1pc

E





1pc

HARDWARE LIST

1		8pcs	2		5pcs	3		1pc	
M6x15			M6x20			4x4			
4		1pc	5		2pcs	6		1pc	
M4x37									
7		1pc							



Do not tighten screws until completely assembled.

STEP 1.



1	M6x15		2pcs
---	-------	---	------



STEP 3.




2	M6x20		4pcs
5			1pc

STEP 2.

2-1





2-2




1	M6x15		4pcs
2	M6x20		1pc

STEP 4.




1	M6x15		2pcs
---	-------	---	------

STEP 5.




4		1pc
5		1pc
6		1pc

STEP 6.




To Prevent Tip over
Product Must Be
Attached To Wall



7		1pc
---	---	-----

ASSEMBLY INSTRUCTIONS



Do not tighten screws until completely assembled.

PARTS IDENTIFICATION


HARDWARE LIST

A



1pc

B




1pc

C



1pc


D




1pc

1		4pcs
M6x12		
2		1pc
M8x15		
3		4pcs
M5x25		
4		1pc
4x4		
5		1pc
5x5		


STEP 1.



1-1




1-2




1		4pcs
M6x12		
2		1pc
M8x15		

STEP 2.



SCREWDRIVER
(NOT PROVIDED)



3		4pcs
M5x25		