




ASSEMBLY INSTRUCTION

MF313427/313428

















Minimum no. 2 of people
recommended to assemble
this product: Approx.
assembly time: 60 mins





























PART LIST 313427

4	 1PC	5	 1PC	6	 1PC
7	 1PC	8	 1PC	13	 2PCS
14	 1PC	15	 1PC	16	 1PC
17	 1PC	19	 1PC	20	 2PCS
22	 9PCS	23	 4PCS	24	 4PCS


HARDWARE LIST 313427


A	 M $\frac{1}{4}$ "X50 16PCS	B	 M $\frac{1}{4}$ "X40 4PCS	C	 M $\frac{1}{4}$ "X35 6PCS	D	 M $\frac{1}{4}$ "X25 36PCS
E	 M $\frac{1}{4}$ "X15 38PCS	F	 $\frac{1}{4}$ "x7 4PCS	G	 #30x30x13 6PCS	H	 M3.5x15 2PCS
i	 174x55x45H 1PC	J	 M4X23X57 1PC	K	 M4x15 54PCS	L	 M4x15 32 PCS
M	 15x20x40H 16 PCS	N	 3x50x50 8PCS	O	 Ø15x12 12PCS	P	 Ø7x40 12PCS
Q	 Ø6x24 8PCS	R	 30x50x95 1PC	S	 22x35x50 1PC	T	 5x13x1532 1PC
U	 remote control 1PC						

PART LIST 313428


1  1PC	2  1PC	3  1PC
18  2PC	21  4PCS	9  FRONT 1PC
10  1PC	11  1PC	12  FRONT 1PC
25  4PCS	26  4PCS	27  4PCS
28  4PCS		

STEP 1




A	G
 M $\frac{1}{4}$ "x50	 #30x30x13
8 PCS	4 PCS



STEP 2




A
 M $\frac{1}{4}$ "x50
4 PCS




STEP 3

K

M4x15
8 PCS





STEP 4

T	P
	
5x13x1532	Ø7x40
1PC	12 PCS






STEP 5

O
 Ø15x12
12 PCS




STEP 6

K
 M4x15
14 PCS




STEP 7


Q
 Ø6x24
8PCS





STEP 8




STEP 9

K
 M4x15
4 PCS






STEP 10




E

M $\frac{1}{4}$ "x15

4 PCS





STEP 11



B

M $\frac{1}{4}$ "x40



4 PCS



STEP 12



2 SET

C	F
 M1/4x35	 1/4"x7
4 PCS	4 PCS



STEP 13

E	N
 M1/4x15	 3x50x50
16 PCS	8PCS





STEP 14

E




M $\frac{1}{4}$ "x15

8 PCS






STEP 15

A	C	E	G
 M1/4x50	 M1/4x35	 M $\frac{1}{4}$ "x15	 #30x30x13
4 PCS	2 PCS	10 PCS	2 PCS




STEP 16


H	i
	
M3.5x15	174x55x45H
2 PCS	1 PC




STEP 17




Remove the
outer layer of
paper





Stick it to the
back plate


S
 22x35x50
1PC



STEP 18





R
 30x50x95
1PC



STEP 19

4 SET



M	L
 15x20x40H	 M4x15
16 PCS	32 PCS



STEP 20

4 SET



D
 M $\frac{1}{4}$ "X25
36 PCS



STEP 21


4 SET

K
 M4x15
28 PCS



STEP 22

U



remote
control

1PC

