


ASSEMBLY INSTRUCTION


- COUNTER HEIGHT TABLE

DO NOT FULLY TIGHTEN BOLTS UNTIL THE ENTIRE ITEM IS COMPLETELY ASSEMBLED


A=1 PC




B=2 PCS



C=1 PC




D=2 PCS




No.	Description		Q.TY
1	BOLT Ø 5/16" X45mm		08 PCS
2	FLAT WASHER		12 PCS
3	SPRING WASHER		12 PCS
4	BOLT Ø 1/4" X45mm		04 PCS
5	ALLEN KEY		1 PC


STEP 1



STEP 2



STEP 3



COMPLETE

