
ASSEMBLY INSTRUCTION

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Identify and count all parts and compare with the parts List Below:




CLEANING INSTRUCTION


lean the surface with a furniture polish and a soft cloth.

ASSEMBLY INSTRUCTION

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Identify and count all parts and compare with the parts List Below:





HARDWARE LIST			
NO.	Drawing	Description	Q'ty
Α	OP/IENDONIES	Threaded Bolt Ø5/16" X3 1/2"	8pcs
В	0	Flat washer (Ø5/16"x19mm)	8pcs
С	0	Spring washer (Ø5/16")	8pcs
D	(3)	Hex Nut (Ø5/16")	8pcs
Е	=======================================	Ø5/16" Wrench(12mm)	1pc
F	cumus.	Wood screw Ø8 x 1"	10pcs











Clean the Bed surface with a furniture polish and a soft cloth.