





1 / 3



1 / 2



1 / 2


Ø 7 x 50 mm



A

8

M6 x 60mm



M

8




M6

N

8

Ø 3,5 x 25mm



O

24




Ø 10 x 35 mm

R


4

Ø 4 x 40 mm



H

4



TR Ø 4 x 15 mm

I

10



J

10



K

5



L

1



P

2



Ø 3,5 x 15mm


Q

4




S


4




T



1





N° PIECE	QTE	Longueur	Largeur		 
20	2	948	370	1/3	1/2
21	2	1890	180	1/3	1/2
22	12	895	70	1/3	1/2
23	1	1880	125	1/3	1/2
24	2	123	610	1/3	1/2
27	1	1880	123	1/3	1/2
25	2	1847	312	1/3	1/2
26	1	1832	65	1/3	1/2




1 **x2**




2




3




Ø 3,5 x 25mm




68,50mm




4




Ø 3,5 x 25mm




83mm






5

TR Ø 4 x 15 mm


 $I \times 8$  $K \times 4$ 

6



Ø 7 x 50 mm

 $A \times 4$  L 


7




8



9


 **J** x 10


10

 **S** x 4


**11****P** x 2

Ø 3,5 x 15mm

**Q** x 4**x2****P**
+
2 x Q