

|                                  |                                |                |                                    |     |
|----------------------------------|--------------------------------|----------------|------------------------------------|-----|
| Ax2                              | Bx2                            | Cx2            | Dx2                                | Ex1 |
|                                  |                                |                |                                    |     |
| Fx1                              | Gx1                            | Hx1            | <br>① x12<br>M7x $\frac{120}{4.7}$ |     |
| <br>② x8<br>M7x $\frac{60}{2.4}$ | <br>③ x2<br>M5x $\frac{50}{2}$ | <br>④ x1<br>M4 | <br>x2<br>mm<br>inch               |     |
| (1)<br>                          |                                | (2)<br>        |                                    |     |
| (3)<br>                          |                                | (4)<br>        |                                    |     |
| (5)<br>                          |                                |                |                                    |     |