

WF312150 WF312151



ASSEMBLY INSTRUCTIONS




PARTS Check that you've received all parts listed below.

BOX: 1/2 WF312150

(1) x 1	(4) x 2		
Head Board	Rails		
(5) x 4	(6) x 10		
Legs	Slats		
03			

PARTS Check that you've received all parts listed below.


BOX: 2/2 WF312151




HARDWARE Check that you've received all hardware listed below.


Hardware List

No.	OUTLOOK	DESC	QTY
A		Bolts 5/16"x30 mm	8
B		Plain washer Ø19x1.5 mm	12
\bigcirc		Spring washer Ø13x1 mm	12
D		Allen key 80x30x4 mm	1
E	Better and the second and the secon	Screws Ø4x30 mm	20
F		Bolts 5/16"x60 mm	4
G		Dowel Ø10x30 mm	2











B x 2

STEP 4




C x 2

D x 1





STEP 7 G x 2 Ģ X2 STEP 8 B x 2 C x 2 D x 1

09



STEP 11







CINISH