



# Parts List



# Hardware

A x 49pcs



B x 49pcs




Φ15x12

C x 6pcs




Φ8x40

D x 48pcs




Φ3.5x14


E x 6pcs




E(CL)



E(CR)




E(DL)




E(DR)

F x 24pcs



G x 24pcs



Φ3.5x35

H x 24pcs




Φ15x10






# Step 5



B x 8pcs




# Step 6




B x 8pcs



# Step 7




# Step 8





B x 11pcs




# Step 9






# Step 10




A x 11pcs




# Step 11





# Step 12



x 3








x 3








# Step 13

# x 6



# Step 14



# Step 15

