






Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark. To its left, a box contains an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used.
- Warning 2:** A triangle with an exclamation mark. To its left, a box contains a rectangular block being placed on a surface with a hatched pattern, and a diagram below it showing a screw being inserted into the block.
- Time:** A clock icon with the number **5'** below it, indicating an estimated assembly time of 5 minutes.
- Person:** A stick figure icon with the number **1** below it, indicating that one person is required for assembly.



!



2

