



HARDWARE



- 1. CHECK CAREFULLY FOR SMALL PARTS WHICH MAY COME LOOSE DURING SHIPMENT.
- 2. REMOVE ALL COMPONENTS FROM THE PACK AND PLACE ON A CLEAN, SOFT SURFACE TO ASSEMBLE.
- 3. UNITS SHOULD BE ASSEMBLED BY TWO OR MORE PEOPLE.
- 4. DO NOT OVER TIGHTEN SCREW/ BOLTS UNTIL ASSEMBLY IS COMPLETED.
- 5. WITH USE, SCREW/ BOLT MAY BE COME LOOSE & MUST BE TIGHTENED PERIODICALLY.



STEP 1 (x1)



STEP 2 (x1)

