















Assembly Instructions




Product Diagram/ Produktdiagramm/ Diagramme duproduit/
Diagrama del producto/ Diagramma del prodotto/ 組み立て図



Hardware List/ Hardwareliste/ Liste du matériel/ Lista de hardware/ Elenco dell'hardware/ ハードウェア

(A) × 38  Φ 6×35mm	(B) × 26  Φ 15*12mm	(C) × 12  Φ 15*10mm
(D) × 20  Φ 8*30mm	(E) × 8 	(F) × 8  Φ 3*18mm
(G) × 1  孔距128mm	(H) × 2  M4*16mm	(J) × 4 
(K) × 3  12', 300mm	(L) × 38  Φ 3.5*11mm	(M) × 1 
(N) × 2 	(P) × 1 	(Q) × 4  M6*25mm
(R) × 4  M6*12mm	(S) × 12  Φ 4*40mm	(T) × 1 
(U) × 1  Φ 5*38mm		





Step 1




A×8



D×2




Step 2




A×2





D×2







K×6




L×18




Please fasten the screws through these holes for this step




Step 3



B×6



Step 4




A×6







B×4





D×6




U×1







Arrow




Step 5




Bx4






Step 6




B×2





D×2




Step 7




D×6



Step 8






A×10




M×1



Q×4




Step 9



B×4




D×2




G×1




H×2




L×2





P×1




Step 10




B×6




Step 11



J×4




N×2




Step 12



R×4








Step 13




A×12




C×12




Step 14





K×6





L×18




S×12




Please fasten the screws through these holes for this step



Step 15



Step 16



E×8



F×8



T×1

