

ASSEMBLY INSTRUCTIONS

EASTERN KING (12+4+8)

(Box 1)

BOX OF HEADBOARD & FOOTBOARD

No	ITEM	Qty
A	Headboard	1 pc
B	Footboard	1 pc
C	Headboard Leg	2 pcs
D	Bed Slats	12 pcs
E	Bed Center Slats	4 pcs
F	Bed Slats Support	8 pcs
G	Side Rail(A)-Left	2 pcs
H	Side Rail(B)-Right	2 pcs
I	Bed Side Rail Leg	2 pcs


(Box 1)

HARDWARE LIST

No	ITEM	Qty
1	JCBC M6 x 35mm	12 pcs
2	SPRING WASHER 1/4" Rbw	12 pcs
3	Flat Washer 1/4"ID x 13mmOD Blk	12 pcs
4	ALLEN KEY m4x65mm Blk	1 pc
5	ALLEN KEY m5x65mm Blk	1 pc
6	Flat Head Chipboard Screw m4x32mm Rbw	32 pcs
7	JCBC M6 x 50mm	8 pcs


STEP 1.1 : Attach Head Board Leg (C) to Head Board (A) as shown using JCBC BOLT(1)with Spring Washer (2), Flat washer (3)and securing with ALLEN KEY (4) .

STEP 1.2 : Fix the other holes with Csk Screw (6) as shown.



STEP 2.1 : Attach Side Rail (G) & (H) to the Bed Side Rail Leg (I) as shown using JCBC BOLT(1)with Spring Washer (2),Flat washer (3)and securing with ALLEN KEY (4) by outside side rail (G) & (H) .

STEP 2.2 : Hook SET-UPSIDE RAIL TO HEAD BOARD (A) closely and push down to fit. repeat step 2 with other end of rail to hook onto FOOTBOARD (B).





NOTE : MUST TIGHTEN SCREWS PERIODCALLY WITH USE SCREW WILL BECOME LOOSE CHECK TIGHTNESS OF ALL SCREW EVERY 6-8 WEEKS.

PAGE 1 OF 2

ASSEMBLY INSTRUCTIONS

STEP 3 : Fix the Bed Slat Support Leg (F), to Bed Slat (D) and Center slat (E) as shown . Install the bed slat (D) to side rail (G) & (H) and tighten with Csk Screw (6) as per diagram shown. (NOTE: THE SETUP MUST DONE AT THE DECIDED LOCATION FOR THE BED TO OBTAIN PERFECT STABILITY)
Repeat step 4 for other set of slats assembly.



COMPLETE ASSEMBLY

NOTE : MUST TIGHTEN SCREWS PERIODCALLY WITH USE SCREW WILL BECOME LOOSE CHECK TIGHTNESS OF ALL SCREW EVERY 6-8 WEEKS.