



Veil™ | K-20705-N

38-1/2" oval vessel bathroom sink, no overflow

Features

- Large asymmetrical oval basin
- Trough-style basin allows for two-faucet application or striking large vanity installation
- No faucet holes; requires wall- or counter-mount faucet
- Includes color-matched brass drain cover
- Coordinates with other products in the Veil collection



Available Colors/Finishes

Color tiles intended for reference only.

	0	White
	96	Biscuit
	7	Black Black



1-800-4KOHLER (1-800-456-4537)
Kohler Co. reserves the right to make revisions without notice to product specifications.
For the most current specification sheet, go to www.kohler.com USA or www.kohler.ca Canada.
7-29-2026 22:17 - US-CA

THE BOLD LOOK
OF **KOHLER**®

Codes/Standards

ADA, OBC, CSA B651 compliant when installed to the specific requirements of these regulations.

ADA CSA B651 OBC

ASME A112.19.2/CSA B45.1

ADA

ICC/ANSI A117.1

CSA B651

OBC

Technical Information

Drain Hole Diameter:	1-3/4" (44 mm)
Basin Configuration:	Single Bowl
Basin Length:	37-7/8" (962 mm)
Basin Width:	15-1/2" (393 mm)
Basin Depth:	3-1/2" (89 mm)

Material

- Fireclay

Recommended Products/Accessories

K-23726 Drain treatment

K-23725 Cast iron cleaner

Required Products/Accessories

- K-33151 Clicker drain without overflow
- K-7114 Premier pop-up drain, exposed, without overflow

Warranty

See website for detailed warranty information.

KOHLER® One-Year Limited Warranty





1-800-4KOHLER (1-800-456-4537)



Kohler Co. reserves the right to make revisions without notice to product specifications.

For the most current specification sheet, go to www.kohler.com USA or www.kohler.ca Canada.

7-29-2026 22:17 - US-CA



Recommended ADA Installation



Installation

- Vessel

Installation Notes

Install this product according to the installation instructions.

NOTICE: Countertop manufacturer or cutter must use the cut-out template provided with the product, or a current one provided by Kohler Co. (call 1-800-4-KOHLER). Kohler Co. is not responsible for cutout errors when the incorrect cut-out template is used.

ADA, OBC, CSA B651 compliant when installed to the specific requirements of these regulations.

