










| | | |
|--|--|--|
| An icon showing an L-shaped metal bracket inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used. | A warning triangle containing an exclamation mark. | A clock face showing approximately 1:50. |
| An icon showing a rectangular block on a surface with a hatched pattern. To its right is a block with a screw being inserted, with a diagonal line through it, indicating it should not be used. | A warning triangle containing an exclamation mark. | A simple line drawing of a person. |

20'







2



1



2



3

