



Installation Instruction


Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.




PART LIST




①x 2PCS



②x 2PCS



③x 1PC




④x 1PC




⑤x 1PC



⑥x 1PC




⑦x 5PCS




⑧x 5PCS




⑨x 4PCS




⑩x 1PC




⑪x 1PC



⑫x 4PCS




⑬x 4PCS




⑭x 4PCS


HARDWARE LIST




M6*10mm
A x 17+1PCS




M6*28mm
B x 65+2PCS




Ø5*45mm
C x 12+1PCS




D x 2+1PCS




E x 7PCS




F x 2PCS



Ø6*30
G x 10+3PCS




M3
H x 1PC




M4
I x 1PC

1


X2



2




3




E×1PC
6×1PC

4




A×1PC
I×1PC
5×1PC
6×1PC

5





X2




A x 4 PCS
I x 1 PC
1 x 2 PCS
2 x 2 PCS

6



A x 2 PCS
I x 1 PC
3 x 1 PC
4 x 1 PC


7



Bx10PCS
Ix1PC
7 x 5PCS


8

Screw to
the Backward




Bx10PCS
Ix1PC
8 x 5PCS


9



10




11




Bx20PCS
Gx8PCS
Ix1PC
13 x3PCS
10 x1PC

12




Bx16PCS
Ix1PC
14 x3PCS
11 x1PC

13



C×8PCS
H×1PC
12 ×4PCS


14



C×4PCS
H×1PC
5 ×1PC
6 ×1PC

P10/11

15



16

