













INSTALLATION INSTRUCTIONS



PANRTS LIST

PARSTS LIST			HARDW ARE LIST		
NO.	DESCRIPTION	QTY	NO.	DESCRIPTION	QTY
A		1	H		4
B		1	I		4
C		1	J		4
D		1	K		4
E		1	L		4
F		2	M		1
G		2			





PARST'S LIST			HARDWARE LIST		
NO.	DESCRIPTION	QTY	NO.	DESCRIPTION	QTY
a		18	h		8
b		26	i		8
c		26	j		20
d		24	k		4
e		4	l		4
f		8	m		1
g		48	n		4



STEP 1




STEP 2




STEP 3



STEP 4




STEP 5



STEP 6

	aX4		dX4
---	-----	---	-----




STEP 7



kX4



jX20




STEP 8



hX8




iX8




STEP 9

	aX4		dX10		cX10		fX4
	eX2		bX10				


1




2



3



4




X2


STEP 10

	aX4		dX10		cX10		fX4
	eX2		bX10				


1




2



3




4



X2

STEP 11


 nX4  gX24





STEP 12

 mX1

WALL



STEP 13



STEP 14

