







Assembly Instructions





 60 MIN	 	
---	---	---



A  M4X8 x24	B  M5X8 x8	C  x4	D  x2	E  M6X45 x8
F  x2	G  x2	H  x2	I  M5X50 x2	

1





B




M5X8
x8



2





E



M6X45
x8



3







A






M4X8
x8







4






5



6






7




8

6

7



9



10

